## **EAST Search History**

| Ref<br># | Hits | Search Query   | DBs   | Default<br>Operator | Plurals | Time Stamp       |
|----------|------|--|---|---------------------|---------|------------------|
| L1       | 193  | ((52/220.8) or (52/219) or (174/58) or (220/4.02,3.6) or (137/360)). CCLS.                                       | US-PGPUB  | OR                  | OFF     | 2007/08/04 16:52 |
| L2       | 0    | (wall device receiving fittings uprights horizontal vertical longitudinal cavity channel abutment clamping).clm. | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | AND                 | OFF     | 2007/08/04 16:53 |
| S1       | 472  | (52/22 <sub>0</sub> .8).CCLS.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | OFF     | 2007/08/02 13:27 |
| S2       | 397  | (52/219).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | OFF     | 2007/08/02 13:39 |
| S3       | 990  | (174/58).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | OFF     | 2007/08/02 13:44 |
| S4       | 12   | ("2187490" "6101773" "6426904").<br>PN.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | OFF     | 2007/08/03 10:28 |
| S5       | 2181 | (220/3.2-3.6).CCLS.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | OFF     | 2007/08/03 13:14 |
| S6       | 583  | (220/4.02).CCLS.   | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR                  | OFF ·   | 2007/08/03 11:35 |

8/4/2007 4:53:57 PM Page 1

## **EAST Search History**

| S7 | 878 | (137/360).CCLS.  | US-PGPUB;<br>USPAT;<br>USOCR;<br>EPO; JPO;<br>DERWENT;<br>IBM_TDB | OR | OFF | 2007/08/03 13:13 |
|----|-----|--|---|----|-----|------------------|
| S8 | 68  | ("20020134431"   "2636224"   "2777172"   "3180459"   "3240869"   "3691709"   "3782061"   "3841195"   "3949465"   "4224731"   "4435927"   "4531564"   "4535577"   "4564249"   "4578914"   "4637422"   "4685255"   "4694621"   "4716925"   "4726567"   "4856244"   "4894966"   "4942896"   "4986038"   "5038539"   "5058347"   "5070666"   "5105592"   "5155955"   "5253670"   "5261444"   "5277007"   "5287665"   "5287666"   "5311715"   "5351448"   "5394658"   "5394668"   "5412913"   "5423345"   "5449169"   "5465548"   "5490357"   "5548934"   "5561960"   "5772166"   "5787675"   "5806258"   "5953883"   "6035886"   "6732758").PN. OR ("3529388"   "6061910"   "6330773"   "7021013"   "7204267").URPN. | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | OFF | 2007/08/03 13:17 |
| S9 | 161 | (wall adj device) and fittings   | US-PGPUB;<br>USPAT;<br>USOCR                                      | OR | OFF | 2007/08/03 13:17 |

8/4/2007 4:53:57 PM Page 2